

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, October 22, 2019	Project Contact:	Brian Clauto
Spread: Montgomery Co. ATWS 703, 704A 1375, 1446 MP231.04-230.8 MP229.4-229 AR MN270.01 ATWS727	Spread H	Weather (Wet/Dry/Rain):	Rainy

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: Dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- Inspected designated streams and wetlands included: S-C21, S-001, W-C12, S-C36, W-C11, S-F16 A&B, W-F9 FPO, S-F15, S-MN11, S-NN16
- ECD's were in place and functioning at the designated crossings.

Recommend Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: Matthew Grant Date: 11-15-19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Tuesday, October 22, 2019

- Fig. 1 Near MP 231.09 Bradshaw Rd crossing, ECD's in place and functioning.



- Fig. 2 Designated stream crossing S-C21, ECD's in place and functioning.



- Fig. 3 ECD's in place and functioning at ATWS 1375.



- Fig. 4 Near MP 229.4 designated wetland crossing WC-12, ECD's in place and functioning.

